

# UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION 8

999 18<sup>TH</sup> STREET- SUITE 300 DENVER, CO 80202-2466 Phone 800-227-8917 http://www.epa.gov/region08

Ref: 8EPR-SR

June 14, 2006

MANUEL HERNANDEZ & ANGELINA GALLEGO 3517 GAYLORD ST DENVER, CO 80205

RE: 3517 GAYLORD STREET

Dear Owner.

As part of the VB/I-70 Superfund Site investigation, we recently took soil samples at your property to find out if there is too much lead or arsenic in your yard. The results show that your property does not require a cleanup. The levels of both lead and arsenic are below our cleanup levels. The soil sampling results for your property are as follows:

ADDRESS: 3517 GAYLORD STREET	EPA Cleanup Levels
Lead	
97 parts per million (ppm)	above 400 ppm
Arsenic	
6 ppm	above 70 ppm

This means that your property is not considered by EPA to be part of the VB/I-70 Superfund Site. EPA does not believe that further measures are necessary. You and your family are not at significant risk from arsenic through ordinary contact with soil in your yard while playing, working, gardening, etc. Please note that there may be small areas in your yard, particularly near your house, that may have higher levels of lead due to peeling, external lead-based paint. EPA encourages all owners of older properties to take reasonable precautions regarding lead-based paint.

For further information, please feel free to contact EPA Community Involvement Coordinators Jennifer Chergo at (303) 312-6601 or Patricia Courtney at (303) 312-6631.

Sincerely,

Victor Ketellapper

Remedial Project Manager

The Environmental Protection Agency, Region 8

# Evergreen Analytical, Inc.

#### 4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample ID: VB-3517-GL-01 Client Project ID: 213001.01 Date Collected: 5/19/06

Lab Work Order: 06-3260 Lab Sample ID: 06-3260-21 Sample Matrix: Soil

Date Received: 5/23/06

**TOTAL METALS** 

Prep Method: SW3050

Method: SW6020 060602A.B\102SMPL.D Date Prepared: 6/1/06 Lab File ID: **Dilution Factor:** Date Analyzed: 6/2/06 Lab Fraction ID: 06-3260-21A Method Blank: MB-10054 LQL Analytes **CAS Number** Result Units 4.2 0.40 Arsenic 7440-38-2 mg/Kg 65 0.27 mg/Kg Lead 7439-92-1

Analyst

Qualiflers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Approved

LQL - Lower Quantitation Limit

Surr - Surrogate

Definitions: NA - Not Applicable



# Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Client Sample [D: VB-3517-GL-02

Client Project ID: 213001.01 Date Collected: 5/19/06

Lab Work Order: 06-3260 Lab Sample ID: 06-3260-22

Sample Matrix:

Date Received:

Method: SW6020

5/23/06

#### TOTAL METALS

Prep Method: SW3050

Date Prepared: 6/1/06 Lab File ID: 060602A.B\103SMPL.D **Dilution Factor:** 

Date Analyzed: 6/3/06 Method Blank: MB-10054 Lab Fraction ID: 06-3260-22A

Analytes CAS Number Result LQL Units 7440-38-2 0.39 Arsenic 3.8 mg/Kg Lead 7439-92-1 95 0.26 mg/Kg

Approved

Qualiflers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected

X - See case narrative

-Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate

Print Date: 6/5/06

## Evergreen Analytical, Inc.

4036 Youngfield Street, Wheat Ridge, Colorado 80033-3862 (303) 425-6021

Člient Sample ID: VB-3517-GL-03

Client Project ID: 213001.01 Date Collected:

5/19/06 Date Received: 5/23/06 Lab Work Order: 06-3260

Lab Sample ID: 06-3260-23

Sample Matrix: Soil

TOTAL METALS

Method: SW6020 Prep Method: SW3050

Date Prepared: 6/2/06 060605A.B\023SMPL.D Lab File ID: Dilution Factor:

Lab Fraction ID: 06-3260-23A Date Analyzed: 6/5/06 Method Blank: MB-10057

Analytes Result CAS Number LOL Units Arsenic 7440-38-2 5.7 0.39 mg/Kg Lead 7439-92-1 130 0.27 mg/Kg

Approved

Qualifiers: B - Analyte detected in the associated Method Blank, value not subtracted from result

E - Extrapolated value. Value exceeds calibration range

H - Sample analysis exceeded analytical holding time

J - Indicates an estimated value when the compound is detected, but is below the LQL

S - Spike Recovery outside accepted limits

U - Compound analyzed for but not detected


X - See case narrative

\* -Value exceeded the Maximum Contamination Level (MCL), TCLP limit, or if compound is undetected, LQL exceeds MCL.

Definitions: NA - Not Applicable

LQL - Lower Quantitation Limit

Surr - Surrogate





## UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION 8 Victor Ketellapper Phone 800-227-8917 http://www.epa.gov/region08

### CONSENT FOR ACCESS TO PROPERTY

Name: Manuel Hernandez & Angelifa Gallego (or current property owner)

Location of Property: 3517 Gaylord Street

Property ID: 6865

I consent to officers, employees, and authorized representatives of the United States Environmental Protection Agency (EPA) entering and having continued access to the above referenced property for the purpose of taking samples of soil on the Site.

I realize that these actions are undertaken pursuant to EPA's response and enforcement responsibilities under the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA or Superfund), 42 U.S.C. § 9601 et seq.

Angelia a Challegos
Printed Name

30433-48(o')
Phone Number

work 3)4SS-454761

Incolice Colleges

5/8/06 - Date